

# G104 GrinDr

## Description

- 80's Metal Zone overdrive
- Sound ranges from tight lead to ear piercing distortion


## Installation

The G102 The Crunch is designed to be used in the G100 Modular Effect System.

1. Unplug the Base Unit power cord
2. Locate an empty slot
3. Plug the 4-pin socket into an available connector on the BusBoard
4. Place the module in the base unit and secure with two M3x8mm bolts

## Controls

1. Mounting holes
2. External switch jack socket
3. Input jack socket
4. Output jack socket
5. LED, red when effect turned-on
6. Bypass mode switch
7. Volume knob controls overall volume of the effect
8. Tone knob controls the tone of the effect
9. Gain knob controls the level of gain of the effect



## Turning the Effect On/Off


The effect has a relay based true-bypass. The effect can be turned-on by toggling the Bypass-mode switch to the right. In this mode the effect is always on. Toggle the switch to the left to use an external control, like a foot control, to remotely turn-on and turn-off the effect. The external switch control must be of the 'make' type. In either case the red led lights up when the effect is enabled.

## Usage


Run a cable from the guitar to the In jack socket.  
Run a cable from the Out jack socket to the amplifier.  
Start with all controls at 12 o'clock  
Turn-on the effect  
Rotate the Volume knob clockwise to increase the output level and counterclockwise to decrease it  
Rotate the Gain knob clockwise to increase the level of overdrive and counterclockwise to decrease it.  
Rotate the Tone knob clockwise for a brighter sharper tone and turn it counterclockwise to cut high tones.




Examples






Bright Sparkle



Rock On



Screaming Highs



Feel The Sound



ROA Music Corporation

G104 GrinDr